Weathertzalign Assistance Program

Work Order (Bid Form)

WODE		INFORM	ATION
WUKK	UKUEK	INFURIVI	AHUN

Work Order Name:
Work Order Type: Weatherization
Audit Name: MADISON

CLIENT INFORMATION

Client Name: Address:

Client ID:

Alt. Client ID: 16016SW-0577

AGENCY INFORMATION

Agency: SWHRA Agency Phone: (731) 989-5111

Address: 1574 White AVE Fax:

Henderson, TN Email Address:

Agency Contact: Oliver, Jerry Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	WHO ARE A STATE OF THE STATE OF
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-427-6565

Client Name: Work Order (Bid Form) DOE Weatherization Assistant
Client IE ork Order Name Version 8.5.0

Alt. Client ID: 16016SW-0577 Report Run On: 5/15/2010 Page 1 of 7

Measures

	Measure 1 Seal	Ducts			Componen	ts			Inspected
C	Comment Back Be	drooms and Laundry ro	om registe	rs had	high leak ra	ite.			
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Mastic duct booys and chesk for any loose joints and mastic as needed	Each	1					
2	Labor	Labor	Hour						
(Other Detail								
					111111111111111111111111111111111111111				
				Measur	e Sub Total:		3	Sub Total:	
	Field Notes:								

	Measure 2 Infiltration Redctn				Components				
Comment									
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal crown molding in living room, Seal pipes under kitchen sink, Seal up register in all ceiling and wall	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal exhaust vent over cook stove, Seal pipes behind washer and dryer and hole in wall	Each	1					
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal ceiling in pantry over shelfs. Seal crown moling in back bedroom and wall to ceiling in closet.	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Seal around AC in back bedroom. Middle bedroom seal around breaker box and ceiling in closet	Each	1			The state of the s		
8	Labor	Labor	Hour						
9	Construction Materials/Hardwar e	Seal pipes under bath vanity and seal behind tub in closet	Each	1					
10	Labor	Labor	Hour						
11	Construction Materials/Hardwar e	Weather-strip D1 and D2	Each	1				To a second seco	
12	Labor	Labor	Hour						

Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Measure 3 DWF	l Pipe Insulation			Componen	ts			Inspected
Comment				Estimated			Actual	<u></u>
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail		[7		
			Measur	e Sub Total:			Sub Total:	
Field Notes:			4					
111111111111111111111111111111111111111								
11-12-12-12-12-12-12-12-12-12-12-12-12-1								

Measure 4 Attic	Ins. R-30			Componen	ts A1			Inspected	
Comment									
				Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Attic Insulation - Blown Cellulose - Add 10 inches	SqFt	829	Total Control		1			
2 Labor	Labor	Hour	829						
3 Miscellaneous Supplies	Build attic access cover	Each	1						
4 Labor	labor	Hour							
Other Detail		ſ				F			
			Measur	e Sub Total:			Sub Total:		
Measure 5 Wall	Insulation			Component	ts E1,E2, S2,W1		,N2,S1,	Inspected	
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1195						
2 Labor	Labor	Hour	1195						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant Version 8.5.0

Alt. Client ID: 16016SW-0577

Work Order Name

Report Run On: 5/15/2010

Measure 6 DWI	l Tank Insulation			Componen	ts			Inspected
Comment				Estimated			Actual	<u></u>
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail				- F				
] []		
				111111111111111111111111111111111111111			-	
			Measur	e Sub Total:] .	Sub Total:	
	Monitor is Needed			Componen	ts			Inspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail					·	1 ————		
							r	
gastar 1111 - 1111			Measure	e Sub Total:			Sub Total:	

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Alt. Client ID: 16016SW-0577

Work Order Name:

Report Run On: 5/15/2010

Version 8.5.0 Page 6 of 7

Measure 8 Smoke Detector is Needed				Componen	ts	Inspected		
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Smoke detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Oi	der Gra	nd Total:	Transmi	Gran	d Total:	